

To: Steven Brady  
Vice President for Finance and Management

From: Campus Personal Safety Committee

Subject: Campus Lighting Survey  
Conducted November 05, 2004

Date: February 7, 2005

The following are observations and recommendations resulting from the annual survey of Campus by the Campus Personal Safety Committee on November 5, 2004.

1. There is a light out above the overhead door into the BSB sub basement.
2. There is a pole light out at the west outside entrance to the Library by L-Lot
3. There are two pole lights out on the South side of the Library on University Place west of Irving Ave.
4. The committee still feels that there is not enough lighting on the east side of Weiskotten Hall New Library and again recommends lighting in this area. Some type of flood lighting should be installed on the east side of the New Library addition.
5. The first and second light poles along Memorial Drive as you enter from the east at Memorial Drive and Irving at Weiskotten Hall are out. This was previously reported.
6. On Memorial Drive here is a pole light out at the A parking lot.
7. There is a pole light out on Memorial Drive at the walkway to Weiskotten Hall west of A-Lot

8. On Memorial Drive the outside light to the Mortician Entrance is out (5 South UH). The light on the 4 south exit is out as well as a wall light in the same area.. A second wall light is out on the south side of the 7th floor cross over.
9. There is a pole light out near the pit on Memorial Drive. A second pole light is out on Memorial Drive on the south side of the East Wing.
10. The committee continues to believe the CAB on the Irving Avenue side at the entrance is too dark. The Committee would like additional lighting in this area.
11. It was previously reported that the City of Syracuse street light on Niagara Mohawk pole #32 is out and the result is inadequate light on the Adams Street Door. New lights have been installed but one of the new pole lights that is in about the same location as the old is out.