



Lighting Survey – 11/2006

To: Steven Brady
Vice President for Finance and Management

From: Campus Personal Safety Committee

Subject: Campus Lighting Survey
Conducted November 2, 2006

Date: December 6, 2006

The following are observations and recommendations resulting from the annual survey of Campus by the Campus Personal Safety Committee on November 2, 2006.

Silverman Hall:

- Roof light, northeast side – Bad ballast
- Stairs leading from fire door on the northeast corner, need repair.
- South side – stairs on sidewalk leading to west side of bldg. Railing badly in need of repair. Current condition creates a safety hazard.
- Southeast fire door – light out. Light should be replaced with brighter light.

B-4 Lot

- Fuel tank #61 needs pad lock on filler cap cover
- Shrubs and weeds on west side of the lot need to be cut back so parkers can see this area as they approach their vehicles.

Transformer Corral

- Flood lights facing into this area were all out. Should they be on or are they “work lights” turned on during operations? We feel it would be best for these to be on during sun down.
- Barbed wire on top of this fence does not completely circle the corral.

Weiskotten Hall

- Wall light on west side of Anatomy wing – the southern most light – bad ballast.

Corner of Adams & Irving

- Lighting is very poor at this corner particularly since construction began for the VE.

CAB

- Recommend brighter light fixture over door on Irving Ave. side of CAB.

Adams & EB Streets

- Pole light on Adams just east of EB St. has a bad ballast.
- Pole light on EB St. just north of Adams has a bad ballast.

ER

- Recommend adding a “NO LEFT TURN” sign facing the ER be placed on Adams St. Only one small “One Way” sign current there.

UH Traffic Circle

- Lighting along the Hospital is very good HOWEVER, lighting on the west side of the circle and in the middle of the circle by the parking spaces is inadequate. New lighting needed.

E-Lot

- Lighting in E-Lot is inadequate. Recommend a light or lights on the roof of the ROC or CWB to be directed into the E-lot. There is no lighting on the north side of the bldg.

Gas Tank

- Lights attached to the gas tank between the CWB and the Gamma Knife are out.

CWB Loading Dock Area

- West wall light on the second bay from the west is out.
- Pole light on the west side of the paved area in front of the CWB dock is out.

UH

- Light on the wall just to the north of the DOCS access door on the south wing is out.